

**That's It Trades Service**

**Phone:** [0476 107 799](tel:0476107799)

**Email:** [admin@thatsit-trades.com.au](mailto:admin@thatsit-trades.com.au)

**Facebook:** [That's It Trades Service - That's It Handyman & Electrical | Cairns QLD | Facebook](#)

**Instagram:** [That's It Trades Service \(@thatsittrades\)](#) • [Instagram photos and videos](#)

**Website:** <https://thatsithandyman.com.au>

**ABN:** [91 864 616 592](#)

**Electrical Contractor Licence:** [90233](#)

**Security Provider Licence:** [4705365](#)

**That's It Trades Service** is a family-owned business in Cairns Northern Beaches.

We provide quotes & completed projects all over the Cairns Region.

We are licensed & insured.

The information below is designed to guide our Clients on why updating all smoke alarms within a dwelling is required. The information provided below is on the Queensland Fire & Emergency Services website. [www.qfes.qld.gov.au](http://www.qfes.qld.gov.au). Please visit the QFES website for more information.

**EXISTING DWELLINGS FOR OWNERS/OCCUPIERS**

**From 1 January 2017**

When replacing smoke alarms, they must be of a photoelectric type, which complies with Australian Standard (AS) 3786-2014.

Existing smoke alarms manufactured more than ten years ago must be replaced. (Note: Smoke alarms should have the date of manufacture stamped on them).

Smoke alarms that do not operate when tested must be replaced immediately.

Existing hardwired smoke alarms that need replacement must be replaced with a hardwired smoke alarm.

**From 1 January 2027**

Smoke alarms in all dwellings must:

- i)** be photoelectric (AS 3786-2014); and
- ii)** not also contain an ionisation sensor; and
- iii)** be less than ten years old; and
- iv)** operate when tested; and
- v)** be interconnected with every other smoke alarm in the dwelling to activate together. Smoke alarms must be installed on each storey:
  - i)** in each bedroom; and
  - ii)** in hallways that connect bedrooms and the rest of the dwelling; or
  - iii)** if there is no hallway between the bedrooms and other parts of the storey; and

- iv) if there are no bedrooms on a storey, at least one smoke alarm must be installed in the most likely path of travel to exit the dwelling. Smoke alarms must be either hardwired or powered by a non-removable 10-year battery, or a combination of both may be allowed.

#### **DWELLINGS BEING SOLD, LEASED OR AN EXISTING LEASE IS RENEWED**

##### **From 1 January 2017**

Requirements for existing dwellings:

Existing landlords' and tenants' obligations regarding installing and testing smoke alarms continue.

Property sellers must continue to lodge a Form 24 with the Queensland Land Registry Office stating that the requirements of the smoke alarm legislation have been met.

##### **From 1 January 2022**

Smoke alarms in the dwelling must:

- i) be photoelectric (AS 3786-2014); and
- ii) not also contain an ionisation sensor; and
- iii) be less than ten years old; and
- iv) operate when tested; and
- v) be interconnected with every other smoke alarm in the dwelling to activate together.

Smoke alarms must be installed on each storey:

- i) in each bedroom; and
- ii) in hallways that connect bedrooms and the rest of the dwelling; or
- iii) if there is no hallway between the bedrooms and other parts of the storey; and
- iv) if there are no bedrooms on a storey, at least one smoke alarm must be installed in the most likely path of travel to exit the dwelling. Smoke alarms must be hardwired or powered by a non-removable 10-year battery, or a combination of both may be allowed.

#### **NEW DWELLINGS AND DWELLINGS BEING SUBSTANTIALLY RENOVATED**

##### **From 1 January 2017**

The development approval process for new dwellings and substantial renovations will ensure that building approvals received on or after this date will bring dwellings into compliance with the new laws.

Smoke alarms in the dwelling must:

- i) be photoelectric (AS 3786-2014); and
- ii) not also contain an ionisation sensor; and
- iii) be hardwired to the mains power supply with a secondary power source (i.e. battery); and
- iv) be interconnected with every other smoke alarm in the dwelling to activate together.

Smoke alarms must be installed on each storey:

- i) in each bedroom; and
- ii) in hallways that connect bedrooms and the rest of the dwelling; or
- iii) if there is no hallway between the bedrooms and other parts of the storey; and

- iv) if there are no bedrooms on a storey, at least one smoke alarm must be installed in the most likely path of travel to exit the dwelling.

### PREScribed LOCATIONS FOR INSTALLING SMOKE ALARMS

Where practicable, smoke alarms must be placed on the ceiling. Smoke alarms must not be placed:

- i) within 300mm of a corner of a ceiling and a wall;
- ii) within 300mm of a light fitting;
- iii) within 400mm of an air-conditioning vent;
- iv) within 400mm of the blades of a ceiling fan. There are special requirements for stairways, sloping ceilings, and ceilings with exposed beams. These requirements are explained in the Building Fire Safety Regulation 2008. Penalties may be imposed for non-compliance with the law

### GLOSSARY OF TERMS\*

**Dwellings:** houses, townhouses (Class 1A) and units (Class 2).

**Photoelectric:** the method the device uses to detect smoke.

**Hardwired:** connected to the domestic dwelling's electricity supply.

**Interconnected:** if one smoke alarm sounds, all the other smoke alarms will also sound.

Interconnection can be wired or wireless.

**Storey:** a space within a building between one floor level and the floor level or roof above.

\*Refer to specific legislation for full definitions.

